



How to Measure your Clothing

Garment Sizes	lnches	Centimetres
Small	34-36	86 – 92
Medium	38-40	97 – 102
Large	42-44	107 – 112
X-Large	46-48	117 – 122
2XL	50-52	127 – 132
3XL	54-56	137 - 142

Product European Norms





EN ISO 20471:2013 EN 343:2003 + A1:2007



All about the product ...

The GN400Y Hi-Vis Bomber is a fundamental garment to ensure workers safety and comfort.

Features and benefits

- Heavyweight polyester oxford outer shell with PU coating
- Press stud flag
- Quilted lining
- Full taped seams
- 2 Lower front pockets with flaps
- Internal breast pocket
- Concealed head/ drawcord in collar

Sizes: S - 3XL

Area to Measure	Measurement format
Chest	S,M,L,XL,2XL,3XL



Bespoke this garment with our heat seal/embroidery logo lab!









For more information contact us:
T: +44 (0) 121 359 8880 F: +44 (0) 121 359 8484
E: sales@bodyguardworkwear.co.uk
www.bodyguardworkwear.co.uk